



ECOL₂
Energy
Controlled
Leather

Bader de Mexico S.en C.por A. de C.V.
Delta Plant
Calle Sigma No. 601-Fracc. Industrial Delta
León Gto. 37545
Mexico

produces at its site in an energy-efficient process and calculates the
Corporate Carbon Footprint in accordance with
the ECO₂L-calculation tool.

Registered audit number: 024
Category of production: wet blue/wet white to finished leather
Audit record: ECO₂L 7.4-2013


Auditor: Dipl.-Ing. Jutta Knödler

Audit date: January 27, 2016

Audit valid until: January 27, 2019

FILK Forschungsinstitut
Leder und Kunststoffbahnen

Research Institute of Leather and
Plastic Sheeting (FILK) gGmbH
Meißner Ring 1-5, 09599 Freiberg, Germany
Phone: +49 (0)3731 366-0
Fax: +49 (0)3731 366-130